


Part - 1

**Performa For The Safety School Building**  
(To be filled by the Head of School / Institute)

1. Name of School Guru Nanak Model Sr. Sec School
2. Location Parbhat Nagar, Dholewal, Ludhiana
3. Plot Area 12639.63 Sq. ft.
4. Plinth Area G.F.:- 8628.33 Sq. ft, F.F.:- 8628.33 Sq. ft, S.F.:- 7057.6 Sq. ft.
5. Number of Storey Total Card Area:- 24314.26 Sq. ft.
6. Year of Construction of building Year 1996
7. Supervision of the qualified Engineer,  
The following details may be given:
  - a) Name of the Engineer Mr. Gobinda Malik
  - b) Address Upkar Nagar, Main Road, Kundan Pura
  - c) Set of Structure Drawing used in the construction if available No
  - d) Name of the Architect Malik Engineers and Architects
8. Whether the building has been constructed for the purpose of :
  - a) School ( Yes / No ) Yes
  - b) Residential purpose and converted for use as a school ( Yes / No ) No
9. Materials used for Roof:
  - a) R.C.C. slabs ( Yes / No ) Yes
  - b) R.S. Joists and Battens ( Yes / No ) No
  - c) Wooden Joists and Battens ( Yes / No ) No
10. Materials used for walls:
  - a) Mud Mortar ( Yes / No ) No
  - b) Cement Mortar ( Yes / No ) Yes
  - c) Plaster (i) Lime Mortar ( Yes / No ) No  
(ii) Cement Mortar ( Yes / No ) Yes
11. Flooring :
  - a) Conglomerate ( Yes / No ) No
  - b) Terrazzo / Chips & Tiles ( Yes / No ) Yes
  - c) Brick Paving ( Yes / No ) No
12. Detailed Drawing indicating dimensions of the rooms along with size and location of doors and windows Attached

Signature with stamp of  
The Head of the School / Institute

  
Principal,

Guru Nanak Model Sr. Sec. School (Recognised)

Parbhat Nagar, Dholewal, Ludhiana-03

ID. No. L.S.-4397

Part-II  
(To be filled by S.D.E. of P.W.D. B&R Department)

I have visited the above mentioned school on 14/5/25 and have visually inspected it from all angles of safety and I found it fit for normal use as school building.

In case any addition / alteration of expansion and modification of this building is to be carried out the same be carried out under the supervision of a technically specified Engineer and this certificate may again be obtained after the completion of work from the undersigned.

In case the building is affected by flood or if there is settlement of walls / foundations or caves of roof etc. immediately inspection of the undersigned be arranged to check the stability and safety of the building.

The Area as written in the application form has been verified and found correct as per site.

The fee submitted is correct as per built up area of School and Govt. notification for fees.

The fee deposited by the School has been verified on portal. *by account branch*

This building can be safety occupied for normal use up to 31/3/26 (indicate year up to which it can be used).

*[Signature]*  
Sub Divisional Engineer  
Sub Divisional Engineer  
Provincial Sub Division No.  
P.W.D. B&R E. LUDHIANA.